Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 119

Date :- 20/6/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE B.B.M.P Yelahanka
2	AREA	Pondurenga Survey Purl
3	LOCATION	Near. B.B.M.P office
4	CONDITION OF GROUND WATER	natural water
5	OPTIMUM DIA OF THE BOREWELL	6 1/2"
6	DEPTH RECOMMENDED	1000 to 1200
7	APPROXIMATE YIELD EXPECTED	2 1/2"
8	QUALITYOF WATER	Good
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	500-800-1100
10	CASING EXPECTED APPROXIMATELY	180 to 200
11	RAIN WATER HARVESTING ADVISED OR NOT	— NO —
12	REMARKS	— NO —

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Yelahanka Zone)
Yelahanka, Bangalore

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 108

Date :- 28/4/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE B.B.M.P. Yelahanka
2	AREA	Srinivas Pura
3	LOCATION	Maariyamma Temple
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6½"
6	DEPTH RECOMMENDED	1000 to 1300
7	APPROXIMATE YIELD EXPECTED	3"
8	QUALITYOF WATER	Normal
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	850 - 1100 - 1250
10	CASING EXPECTED APPROXIMATELY	100 to 120
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No- 104

Date :- 25/4/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	B.B.M.P. AEE. Yelahanka
2	AREA	Yelahanka old town
3	LOCATION	Chodeswari Temple
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6½"
6	DEPTH RECOMMENDED	1000 to 1200
7	APPROXIMATE YIELD EXPECTED	2"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	650 ≠ 900
10	CASING EXPECTED APPROXIMATELY	200 to 220
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No- 102 Date :- 20/3/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	A.E.E BBMP Yelahanka
2	AREA	Yelahanka old town
3	LOCATION	Lake
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6 1/2"
6	DEPTH RECOMMENDED	900 to 1100
7	APPROXIMATE YIELD EXPECTED	2"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	750-950
10	CASING EXPECTED APPROXIMATELY	190 to 210
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 101

Date :- 20/8/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE BBMP Yelahanka
2	AREA	Bogalur Cross
3	LOCATION	Udayanagar
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6½"
6	DEPTH RECOMMENDED	1100 to 1300
7	APPROXIMATE YIELD EXPECTED	2½"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	500-850-1150
10	CASING EXPECTED APPROXIMATELY	165 to 185
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

SRI KALABYRAVA ELECTRICALS

Govt. Licenced Electrical Contractor

Down Bazar Road, Yelahanka, Bengaluru - 64
Mob: 9342175592

Ref:

Date:

CASH BILL

To,
Assistant Executive Engineer,
Yelahanka Satellite Town Sub Division,
BBMP, Bangalore.

Sir,

Sub:-Drilling of bore wells and providing water supply facilities to ward No:01, 02, 03 & 04.

******

The details of amount paid for getting power supply to the Near Bande Maramma Temple, Srinivaspura, Yelahanka Old Town in ward no:01

Sl.No	Description (RR No)	Amount
1	Application fees for BESCOM	118
2	Deposit towards BESCOM	10500
3	Meter Charges	2430
4	Contractor charges for getting services	4000
	TOTAL	17048

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For SHREE KALABHAIRAVA ELECTRICALS

Proprietor

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No- 135

Date :- 19/7/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE BBMP Yelahanka
.2	AREA	Bettahalli
3	LOCATION	Ambabahalli 2"Main 2"Cross
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6½"
6	DEPTH RECOMMENDED	1000 to 1200
7	APPROXIMATE YIELD EXPECTED	2½"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	800 - 950 - 1100
10	CASING EXPECTED APPROXIMATELY	160 to 180
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಜಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-೨೦೬

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 112

Date :- 10/6/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE B.B.M.P. Yelahanka
2	AREA	Doddabettahalli
3	LOCATION	7th Main
4	CONDITION OF GROUND WATER	Natural water
5	OPTIMUM DIA OF THE BOREWELL	6 1/2"
6	DEPTH RECOMMENDED	800 to 1000
7	APPROXIMATE YIELD EXPECTED	2"
8	QUALITYOF WATER	Normal
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	450-700-950
10	CASING EXPECTED APPROXIMATELY	160 to 180
11	RAIN WATER HARVESTING ADVISED OR NOT	— No —
12	REMARKS	— No —

AE

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-೫೬೦

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No- 109

Date :- 28/4/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE B.B.M.P. Yelahanka
2	AREA	Doddabethehalli
3	LOCATION	Giredanagar
4	CONDITION OF GROUND WATER	Good
5	OPTIMUM DIA OF THE BOREWELL	6½"
6	DEPTH RECOMMENDED	900 to 1100
7	APPROXIMATE YIELD EXPECTED	2"
8	QUALITYOF WATER	Good
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	300+650-900
10	CASING EXPECTED APPROXIMATELY	150 to 170
11	RAIN WATER HARVESTING ADVISED OR NOT	— NO —
12	REMARKS	— NO —

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರ
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 100

Date :- 20/3/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	A.E.E BBMP-Yelahanka
2	AREA	Thick Bettahalli
3	LOCATION	Babaje layout
4	CONDITION OF GROUND WATER	Normal
5	OPTIMUM DIA OF THE BOREWELL	6½
6	DEPTH RECOMMENDED	900 to 1100
7	APPROXIMATE YIELD EXPECTED	2½"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	800 - 900 -
10	CASING EXPECTED APPROXIMATELY	200 to 220
11	RAIN WATER HARVESTING ADVISED OR NOT	—— NO ——
12	REMARKS	—— NO ——

AE

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ.
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Venkatesh
9901671031

GANGADEVI GROUND WATER CONSULTANT

#96,1st Main ,2nd Cross ,Near govt high School, Goraguntepalya
Bangalore -560022

No - 99

Date :- 20/8/2023

REPORT ON GROUND WATER INVESTIGATION

1	NAME OF THE CUSTOMER	AEE BBMP Yelahanka
2	AREA	Bettahalli
3	LOCATION	Ambedkar Road 2nd Main
4	CONDITION OF GROUND WATER	Good.
5	OPTIMUM DIA OF THE BOREWELL	6 1/2"
6	DEPTH RECOMMENDED	1000 to 1200
7	APPROXIMATE YIELD EXPECTED	2"
8	QUALITYOF WATER	Good.
9	APPROMIMATE DEPTH AT WHICH THE WATER IS EXPECTED TO BE MET	950 - 1100
10	CASING EXPECTED APPROXIMATELY	150 to 180
11	RAIN WATER HARVESTING ADVISED OR NOT	— NO —
12	REMARKS	— NO —

AE

Signature of the Deviner

Note: The Survey was carried out by this divining/Geophysical method of Surveying is with our good knowledge and experience, however no gurantee of water will be given

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬ.ಗ.ಪ.ಕಿ, ಬೆಂಗಳೂರು-10.